

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	005	017	0000001165	See list below	Connectors	EC11	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)


List of part numbers affected					
EC11.0001.001.21	EC11.0001.002	EC11.0001.201	EC11.0001.201.21	EC11.0001.202	EC11.0001.206
3-108-659	3-110-861	9900.0001	9900.0002	9900.0004	EC11.0001.001
EC11.0001.301	EC11.0001.301.02	EC11.0001.301.21	EC11.0001.302	EC11.0001.401	EC11.0001.402
EC11.0021.001	EC11.0021.001.21	EC11.0021.002	EC11.0021.201	EC11.0021.201.21	EC11.0021.202
EC11.0021.301	EC11.0021.301.21	EC11.0021.302	EC11.0021.401	EC11.0021.402	EC11.0031.001
EC11.0031.001.21	EC11.0031.002	EC11.0031.201	EC11.0031.201.21	EC11.0031.202	EC11.0031.301
EC11.0031.301.21	EC11.0031.302	EC11.0031.401	EC11.0031.402	EC11.0051.002	

2 Type of change

Change of type and position of markings

3 Detailed description of change

- Markings are new in the moulding tool and not printed on the moulding body any more.
- Position of markings now is on the top side by the line switch.



4 Reason of change

The change is implemented to improve the quality of the product markings.

5 Release date

The change takes effect in ww 24/2019 (Date code 1924 or higher on label) and has no effect on the validity of the approval certificates.

6 Impact of change and recommended action

	Yes	New position and appearance of product markings
Form	Yes	
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet EC11	

Product Change Notification					PCN EC11		D10-037-441
owner	creation date	release date	released by	change order no	rev	page	
huberth	07.06.2019	19.07.2019	limachcl	2017810	A	1 of 1	