

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type			
02	007	013	0000002297	See list below	Connectors	4797 Appliance Outlet 16A 70°

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)







List of part numbers affected				
4797.0000	4797.0010	4797.0012	4797.0015	4797.0025
4797.0030	4797.0100	4797.0110	4797.0112	4797.0115
4797.0120	4797.0125	4797.0130	4797.3010	4797.3012
4797.3015	4797.3020	4797.3030	4797.3100	4797.3110
4797.3112	4797.3115	4797.3120	4797.3125	4797.3130

The part numbers 4797.0020, 4797.3000 and 4797.3025 are not part of this change. The change for said three part numbers will be executed at a later stage.

2 Type of change

Two laterally positioned notches added to the molding body.

3 Detailed description of change

Old product appearance	New product appearance
<p>Screw-on version</p>  	<p>Screw-on version</p>  
<p>Snap-in version</p> 	<p>Snap-in version</p> 

Product Change Notification					PCN - 4797 Cord Retention Notches Added		
owner	creation date	release date	released by	change order no	rev	page	D10-034-720
vetersa	08.07.2019	14.08.2019	limachcl	2017298	B	1 of 2	

4 Reason of change

The notches are implemented as a standard feature to be compatible with side latching cord retention systems such as P-Lock, SecureLock or TwyLock.

5 Release date

The change takes effect in production in ww36/2019 (Production date code 1936 or higher on label). The validity of the approval certificates is not affected by this change.

6 Impact of change and recommended action

Form	Yes	Laterally positioned notches. Fully backwards compatible
Fit	No	-
Function	Yes	Compatibility with side latching cord retention systems
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
4797 - Data Sheet	

Product Change Notification					PCN - 4797 Cord Retention Notches Added		
owner	creation date	release date	released by	change order no	rev	page	D10-034-720
vetersa	08.07.2019	14.08.2019	limachcl	2017298	B	2 of 2	