

### 1 Products affected




| Product hierarchy no. * |     |            | Part no.  | SBU        | Type | Customer part no. |
|-------------------------|-----|------------|-----------|------------|------|-------------------|
| SBU   PG                | PGU | Type       |           |            |      |                   |
| 02   007                | 038 | 0000002289 | 4789.1100 | Connectors | 4789 |                   |
| 02   007                | 038 | 0000002289 | 4789.1200 | Connectors | 4789 |                   |

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

### 2 Type of change

- Country-of-Origin
- Rated voltage
- Cable type
- Standards
- Approvals
- Laser marking

### 3 Detailed description of change

| Type of change                      | Old   |   | New   |                                      |
|-------------------------------------|---|---|---|--------------------------------------|
| Country-of-Origin                   | Czech Republic CZ   |   | China CN  |                                      |
| Rated voltage UL / CSA <sup>1</sup> | 125/250VAC  |   | 250VAC  |                                      |
| Cable type                          | Acc. IEC 60227-5 & IEC 60245-4 SJT  |   | H05VV-F, H05RR-F, H05RN-F SVT, SJT  |                                      |
| Standards                           | UL 498  |   | UL 60320-1  |                                      |
|                                     | CSA C22.2 No. 42  |   | CSA 22.2 No. 60320-1-11   |                                      |
| Approvals                           |  | Canada, CSA Approval mark Combined USA & Canada |    | USA, UL Listed Combined USA & Canada |
| Laser marking                       | N/A   |   | <br>Variant 4789.1100 marked with complete part number |                                      |

<sup>1</sup> Rated voltage according to the new UL 60320-1 standard

| 4789          |            |              |             |                  | 0118.2223 |        |
|---------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date | created by | release date | released by | notification no. | revision  | page   |
| 2014-06-12    | bisanger   | 2014-06-18   | bisanger    | 25521            | -         | 1 of 2 |

#### 4 Reason of change

Changed production site and renewal the approvals; UL changed standard from UL 498 to UL 60320-1

#### 5 Release date

The change will be rolled-out starting ww 10/2015 and lasts approx. 9 months depending on the variant.

#### 6 Impact of change and recommended action

Form: Approval mark, Laser marking  
Fit: Cable type  
Function: Rated voltage  
Production Site: Country-of-Origin  
Product Label: N/A

#### 7 Reference Documents / Attachments

| Kind of document                     | Document number | Remarks |
|--------------------------------------|-----------------|---------|
| <a href="#">Data sheet</a>           |                 |         |
| <a href="#">Mounting Description</a> | 0115.0051       |         |

|               |            |                   |                 |                  |                  |        |
|---------------|------------|-------------------|-----------------|------------------|------------------|--------|
| <b>4789</b>   |            |                   |                 |                  | <b>0118.2223</b> |        |
| creation date | created by | release date      | released by     | notification no. | revision         | page   |
| 2014-06-12    | bisanger   | <b>2014-06-18</b> | <b>bisanger</b> | <b>25521</b>     | -                | 2 of 2 |