

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU Type				
04	019	200	0000008801	4435.XXXX	Protection	TA35 1 Pole
04	019	200	0000008802	4435.XXXX	Protection	TA35 2 Pole
04	019	200	0000008803	4435.XXXX	Protection	TA35 3 Pole
04	019	202	0000008821	4435.XXXX	Protection	TA35 Rotary 1 Pole
04	019	202	0000008822	4435.XXXX	Protection	TA35 Rotary 2 Pole
04	019	202	0000008823	4435.XXXX	Protection	TA35 Rotary 3 Pole

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

Shift of production location to new location.

3 Detailed description of change

Shift of production location from Switzerland to Czech Republic.

Old:

SCHURTER		Part No. 4435.9999		RoHS COMPLIANT (002/19/10)	
CE					
10	Circuit breaker for equipment				
Qty.	TA35-CBDWF200C0		20A		
(1T) Lot No. 1580871	AC 240V / DC 60V				
(9D) Date Code 1136					
SE	(4L) CoO	CH			

New:

SCHURTER		Part No. 4435.9999		RoHS COMPLIANT (002/19/10)	
CE					
10	Circuit breaker for equipment				
Qty.	TA35-CBDWF200C0		20A		
(1T) Lot No. 1580871	AC 240V / DC 60V				
(9D) Date Code 1136					
SE	(4L) CoO	CZ			

4 Reason of change

-

5 Released date

16.09.2011

6 Impact of change and recommended action

Form: -
Fit: -
Function: -
Production Site: -

TA35					0118.2076	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
07.09.2011 07:58:29	MBU	16.09.2011	CVO	22563	_.01	1 von 1